

#### **Advantages**

Made in Canada for Canadian conditions

Rugged 2" curved slats

G90 Galvanized finish that needs no further painting

Structural Angle Guides and Bottom Bar are prime painted

Fluid governor for smooth and quiet operation

Steel Plate Brackets are more durable than stamped steel bracket plates

An economical alternative when a fire door is required to close only during testing or in the event of a fire

Resetting is simple and can be performed by one technician

#### Features

2C curved Slat Curtain, 22 ga. <sup>1</sup>/<sub>4</sub>" Thick Steel Bracket Plates Cast Iron Stops 1 Year Warranty 3/4, 1 1/2, 3, or 4 hour fire labeled

#### Options

Prime painted hood

Optional solenoid release with 30 sec. time delay or 72HR battery backup

Smoke Detectors & sound strobes

Smoke seals

### **Benefits**

Ease of installation and resetting

Ensures years of trouble free operation


Best value for the price






# STAY OPEN FIRE DOOR DETAILS


## **TYPICAL DETAILS**



## **GUIDE DETAILS**








BETWEEN JAMB GUIDES

## AREA CHART



## DOOR CLEARANCE CHART

			Dimensions in Inches					
Area	Slat	А	В	D	W	Х	Y	
1	2C	13″	14″	6″	2 1⁄2″	2 ½″	2 ½″	
2	2C	13″	14″	6″	2 1⁄2″	3″	2 1⁄2″	

Available in sizes up to 13' 6" wide x 12' 0" high Consult factory for oversize doors





#### SERVICE DOOR INDUSTRIES LIMITED 1340 MID-WAY BLVD., MISSISSAUGA, ONTARIO, CANADA L5T 2G8 TEL (905) 670-1200 FAX (905) 670-8830 sales@servicedoor.com

